					lumber: W9127N-05-C-0012			
Columbia River Channel Improvement, RM 10+00 to 11+10, Flavel  Date: 07/09/2005  Jessica Beach co				Jessica Beach cont	ntacted at 10:10.			
Dredging	Sample Point	Depth (ft)	Time	X Coordinate	Y Coordinate	Turbidity (NTU)	DO (Mg/L)	
Load Number	DR-1	20.7	9:45:39	7337669.57	938422.64	8.5		
478	DR-2	19.9	9:50:29	7337254.91	938208.99	27.1	8.3	
Tidal Stage	DR-2R1	20.3	9:50:33	7337233.82	938209.88	29.8	8.3	
Ebb	DR-4	19.8	9:52:18	7336693.03	938609.96	20.0		
Dredge State:	DR-4R1	19.7	9:52:23	7336688.81	938610.14	20.4		
Overflow through	DR-3	18.2	9:54:24	7338021.54	938353.01	6.2		
skimmers and box								
Weather:								
Clear								
Wind:								
0-5 kts								
Seas:								
1'-2'								
<u>Disposal location</u>								
Columbia River DWS								
Remarks: Action Taken:								
Test DR-2 not in compliance, taken in the plume.				Retest DR-2R1 was taken.				
Test DR-4 not in compliance, taken in the plume.			Retest DR-4R1 was taken.					
Test DR-3 not in plume, taken on port side.			Dredge moved away from area where the non-compliance occurred					
	while continuing dredging			dging.				
					=			
Sample Point Key	All Tests Conducted With YSI 6600					Turbidity Compliance	DO Compliance	
DR-1	Background - 100' Up Current, Within 600-Foot of Channel							
DR-2	100' Down Current					OR	OR, WA	
DR-3	300' Radially from point of dredge (Port or Starboard)					WA	Not Required	
DR-4	900' Down Current from point of dredging					WA	Not Required	
Rx	Indicates a Re-Test where (x) is the Re-Test number for that particular point				ticular point			

					lumber: W9127N-05-C-0012			
Columbia River Channel Improvement, RM 10+00 to 11+10, Flavel  Date: 07/09/2005					Jessica Beach contacted at 14:05.			
Dredging	Sample Point	Depth (ft)	Time	X Coordinate	Y Coordinate	Turbidity (NTU)	DO (Mg/L)	
Load Number	DR-1	20.1	13:37:31	7340809.68	938442.21	3.8		
479	DR-2	18.6	13:39:33	7341111.94	938094.87	15.6	8.6	
Tidal Stage	DR-2R1	19.4	13:39:36	7341120.12	938088.45	15.6	8.6	
Flood	DR-4	21.2	13:41:05	7341731.69	938062.70	16.4		
Dredge State:	DR-4R1	21.4	13:41:07	7341735.90	938062.52	15.8		
Overflow through	DR-3	17.8	13:43:37	7340484.03	938535.02	10.7		
skimmers only	DR-3R1	18.1	13:43:41	7340488.51	938540.92	8.9		
Weather:								
Partly Cloudy								
Wind:								
0-5 kts								
<u>Seas:</u>								
0-1'								
<u>Disposal location</u>								
Columbia River DWS								
	Remarks: Action Taken:							
Test DR-2 not in compliance, taken in the plume.				Retest DR-2R1 was taken.				
Test DR-4 not in compliance, taken in the plume.				Retest DR-4R1 was taken.				
, ,				Retest DR-3R1 was taken.				
				Dredge moved away from area where the non-compliance occurred				
			while continuing dre	dging.				
Sample Point Key	All Tests Conducted With YSI 6600				Turbidity Compliance	DO Compliance		
DR-1	Background - 100' Up Current, Within 600-Foot of Channel							
DR-2	100' Down Current					OR	OR, WA	
DR-3	300' Radially from point of dredge (Port or Starboard)					WA	Not Required	
DR-4	900' Down Current from point of dredging				WA	Not Required		
-	II. F (	F ( )	V. d. D. T	at a sale attack	d'a la a a l'at			
Rx	Indicates a Re-	est where (x)	) is the Re-Te	st number for that par	ticular point			

					umber: W9127N-05-C-0012			
Columbia River Channel Improvement, RM 10+00 to 11+10, Flavel  Date: 07/09/2005  Jessica Beach cor					ntacted at 16:45.			
Dredging	Sample Point	Depth (ft)	Time	X Coordinate	Y Coordinate	Turbidity (NTU)	DO (Mg/L)	
Load Number	DR-1	19.2	18:05:49	7340388.77	937778.57	2.0		
480	DR-2	17.3	18:07:52	7340080.26	938077.51	14.4	8.0	
Tidal Stage	DR-2R1	17.2	18:07:55	7340076.30	938083.76	14.2	8.0	
Ebb	DR-4	20.7	18:09:18	7339590.14	938378.03	17.5		
Dredge State:	DR-4R1	20.7	18:09:21	7339590.14	938378.03	16.9		
Overflow through	DR-3	19.2	18:11:20	7340420.47	937728.56	2.3		
skimmers only								
Weather:								
Clear								
<u>Wind:</u>								
0-5 kts								
Seas:								
0-1'								
Disposal location								
Columbia River DWS				_				
Remarks: Action Taken:								
Test DR-2 not in compliance, taken in the plume.				Retest DR-2R1 was taken.				
Test DR-4 not in compliance, taken in the plume.				Retest DR-4R1 was taken.				
Test DR-3 not in plume, taken on stbd side.			Dredge moved away from area where the non-compliance occurred					
	while continuing dredging.			dging.				
0 1 5 :	IAU =	4 13804	(01,000					
	All Tests Conducted With YSI 6600					Turbidity Compliance	DO Compliance	
DR-1	Background - 100' Up Current, Within 600-Foot of Channel					0.5	05 144	
DR-2	100' Down Current					OR	OR, WA	
DR-3	300' Radially from point of dredge (Port or Starboard)				WA	Not Required		
DR-4	900' Down Current from point of dredging				WA	Not Required		
Rx Indicates a Re-Test where (x) is the Re-Test number for that particular point								
Rx	Indicates a Re-I	est where (x)	is the Re-Les	st number for that par	ticular point			